

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

706
East
> 1
1.006 mi.
5313 ft.

SERVICE BOX 35382
3068 CONEY ISLAND AVE
BROOKLYN, NY

NY Spills S106009027
N/A

Relative:
Higher

Actual:
9 ft.

SPILLS:

Name: SERVICE BOX 35382
Address: 3068 CONEY ISLAND AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0208101 / 2003-02-20
Facility ID: 0208101
Facility Type: ER
DER Facility ID: 243705
Site ID: 301576
DEC Region: 2
Spill Cause: Unknown
Spill Class: C4
SWIS: 2401
Spill Date: 2002-11-04
Investigator: KMFOLEY
Referred To: Not reported
Reported to Dept: 2002-11-05
CID: 195
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2002-11-05
Spill Record Last Update: 2003-02-20
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller Company: 999
Contact Name: SEAN MCGEEVER
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was FOLEY Con Ed e2mis #145885: 11/04/02=0830HRS GADSDEN #46009 I&A SERV. REPORTS WHILE DOING INSPECTION IN SB-35382 FOUND APPROX 1-PINT UNKNOWN OIL ON 5 GALLONS OF WATER. IT APPEARS TO BE CONTAINED AT THIS TIME NO SEWERS OR WATERWAYS AFFECTED. NO FIRE OR SMOKE OR PRIVATE PROPERTY INVOLVED. 1-SAMPLE TAKEN ENVIR TAG#35809. CLEANUP PENDING TEST RESULT. 11-04-02 LAB SEQ# 02-10352-001 <1.0 PPM. Update - 11/6/02 1210hrs C. Lugo reports double washed structure with 760 biogen. Removed env. stop tag # 35809. No leaking co. equipment found. Clean up completed. Update - 11/6/02 - 1530 hrs E.O. employee Cuadrado reports sealing a drain in structure with cement. "
Remarks: "1 PINT OF UNKNOWN OIL ON 5 GALLONS OF WATER IN SERVICE BOX. CAR WAS PARKED ON SERVICE BOX AND CON-ED UNABLE TO DO CLEAN UP WITHIN 24 HOUR PERIOD. CON ED SPILL NUMBER 145885."

All Materials:

Site ID: 301576
Operable Unit ID: 859684
Operable Unit: 01
Material ID: 515106

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G
Recovered: .00
Oxygenate: Not reported